

# Firmware Release Log

## NFO Sinus Optimal

### Firmware Releases

The current application firmware version of DSP (motor control), COP (communication and process control) and GUI (user interface) are shown on inverter's display during start-up, and can be viewed in parameter group Versions at any time. For update of firmware, please refer to instruction 190010\_Optimal\_Fw\_Update\_Guide available at [www.nfodrives.se](http://www.nfodrives.se)

Version	Date	Release note
5108	2023-08-23	<u>Market request update:</u> <ul style="list-style-type: none"> <li>Firmware branch based on version 5106 with additional and updated custom settings which are enabled when selecting application type OEM Vacuum Pump.</li> </ul>
5107	2023-08-14	<u>New functionality:</u> <ul style="list-style-type: none"> <li>Firmware with support for control board article no 201700 including: <ul style="list-style-type: none"> <li>Safe Torque Off</li> <li>Configurable digital input functions</li> <li>Software configurable analog voltage/current inputs</li> <li>Fire mode</li> <li>Digital increment/decrement of fixed setpoint</li> <li>Backward compatible with control board 201400</li> </ul> </li> </ul>
5106	2023-03-29	<u>Correction:</u> <ul style="list-style-type: none"> <li>Update AnyBus Compact Com variable map according to order of appearance in corresponding .gsd-file for use with ABCC M30 communication modules.</li> <li>Add single fault tolerance for internal communication to cover for occasional missed packets which could occur when using AnyBus Compact Com M40 modules.</li> <li>GUI error log view screen now displays negative frequencies and negative active power correctly in alarm detailed information.</li> </ul>
5105	2023-02-08	<u>Improvement:</u> <ul style="list-style-type: none"> <li>Await engagement of mains power soft start relay before performing internal cooling fan spin-up after power on, which is useful for units with additional external load connected to inverter's 24V supply to reduce risk of power surge at start up.</li> <li>Faster execution of saving internal data to non-volatile memory at power down, for better accuracy at power blackouts.</li> <li>Raise default thresholds levels for internal high voltage detection, for additional headroom when used on 480Vac supplies.</li> <li>Improve filtering of unstable RUN signal from digital input that may interrupt power stage start up and pre magnetization at beginning of a run sequence.</li> <li>Update/corrections of parameter name definitions in AnyBus communication stack, used in web page access through Profinet connection.</li> <li>Pre-set filter variables for switching frequency</li> </ul>
5104	2022-10-04	<u>Adaptation:</u> <ul style="list-style-type: none"> <li>The tolerance of internal clock oscillator in DSP, which is used when erasing flash memory during firmware update, was found to vary more than anticipated. For some DSP chips with slow oscillator, the delay in COP and GUI was not sufficient. This delay time is now increased. For correct firmware update when going from [5100...5103] → 5104 the sequence must be first COP, then GUI, and lastly DSP.</li> </ul>
5103	2022-09-28	<u>Improvement:</u> <ul style="list-style-type: none"> <li>If installer fails to set <i>Application type</i> at first power up after installation of the unit, a correct tuning will set Application to <i>Ventilation/other</i>, thereby omitting the need for user to deal with the Application select pop-up screen next time power is applied.</li> <li>Added tuning command <i>Confirm</i> to let installer or user confirm motor parameters without actually performing a tuning.</li> </ul> <u>Correction:</u> <ul style="list-style-type: none"> <li>If firmware was updated from 5100 to 5102 (skipping 5101), the user needed to perform a factory reset for parameters from 5101 get their correct default values.</li> </ul>

5102	2022-08-19	<u>Improvement:</u> <ul style="list-style-type: none"> <li>Wider min/max range of motor parameter <i>sigma</i> which is calculated and evaluated during tuning. This is mostly needed for motor types with <math>\cos\varphi \geq 0.85</math>.</li> </ul> <u>Correction:</u> <ul style="list-style-type: none"> <li>When error log is viewed in GUI display and timestamp is <math>\geq 1000</math> h, the line was previously shown with an unwanted linefeed which made the display look garbled.</li> </ul>
5101	2022-05-25	<u>Market request update:</u> <ul style="list-style-type: none"> <li>Selectable analog output ranges (0-10V, 2-10V, etc.) for voltage/current outputs.</li> <li>Improved scaling of analog output voltage when selecting <math>I_{RMS}</math> or <math>P_{OUT}</math> for output.</li> <li>Default (selectable) limitation of setpoint to 50 Hz when running in manual mode.</li> <li>Option to show setpoint and actual value in % instead of Hz.</li> <li>Improved accuracy for PI-reg process regulator when regulating on low values.</li> </ul>
5100	2021-11-22	First release of product application firmware ver 5100.